




# PF/PFC Series Unipolar Motors

## Wiring Diagram and Rotation Chart



	No.	BLK	BRN	ORN	YLW	No.
↓ CW	1	ON	OFF	ON	OFF	4
	2	OFF	ON	ON	OFF	3
	3	OFF	ON	OFF	ON	2
	4	ON	OFF	OFF	ON	1
						↑ CW